E-Stamp Certificate No.IN-PB48372393679523Y issued on 12-05-2026
By PREM NATH Stamp Vendor, Mukerian

ਐਫੀਡੈਵਿਟ

ਮੈਂ ਡਾ. ਸੰਜੀਵ ਚੰਦੇਲ ਪ੍ਰਿੰਸੀਪਲ ਦਸਮੇਸ਼ ਪਬਲਿਕ ਸਕੂਲ, ਬਿਆਨ ਕਰਦਾ ਹਾਂ ਕਿ ਦਸਮੇਸ਼ ਪਬਲਿਕ ਸਕੂਲ ਚੱਕ ਅੱਲਾ ਬਖ਼ਸ਼, ਵਿੱਖੇ ਬੱਚਿਆਂ ਨੂੰ ਲਿਆਉਣ ਅਤੇ ਲੈ ਕੇ ਜਾਣ ਲਈ ਟਰਾਂਸਪੋਰਟ ਦਾ ਹੇਠ ਲਿਖੇ ਅਨੁਸਾਰ ਪ੍ਰਬੰਧ ਹੈ। ਸਕੂਲ ਕੋਲ ਬੱਚਿਆਂ ਨੂੰ ਲਿਆਉਣ ਅਤੇ ਲੈ ਕੇ ਜਾਣ ਲਈ ਬੱਸਾਂ ਦੀ ਗਿਣਤੀ 40 ਹੈ। ਜਿਹਨਾਂ ਦਾ ਰਜਿਸਟ੍ਰੇਸ਼ਨ ਨੰਬਰ

PB07- AB7271, AB9695, AE9695, AF5251, AF9695, AL4541, AS1244, AS1246, AS3203, AS3746, AS3747, AS5763, AS7391, AS8392, BG1394, BG1395, BG1396, BG1806, BG2937, BP7042, BP7043, BP8191, BS6198, BS6200, BV3179, BV2968, BV2983, CA9579, CA9583, CB7178, CB7180, CB8117, CD1574, CD1575, CD4569, CG2482, CJ7016, CJ8642,CL7729 & CN5528

1. ਉਪਰੋਕਤ ਬੱਸਾਂ ਹੋਰ ਟਰਾਂਸਪੋਰਟ ਦੇ ਸਾਧਨਾਂ ਕੋਲ ਫਿਟਨੈਸ ਸਰਟੀਫਿਕੇਟ ਹੈ ਅਤੇ ਇਹ ਸੜਕ ਤੇ ਚੱਲਣ ਯੋਗ ਹਨ।
2. ਉਪਰੋਕਤ ਬੱਸਾਂ ਜਾਂ ਹੋਰ ਟਰਾਂਸਪੋਰਟ ਸਾਧਨਾਂ ਕੋਲ ਪਰਮਿਟ ਹੈ।
3. ਉਪਰੋਕਤ ਗੱਡੀਆਂ ਦੇ ਨਾਲ ਕੰਡਕਟਰ ਵੀ ਹੈ।
4. ਗੱਡੀ ਦਾ ਡਰਾਈਵਰ ਅਤੇ ਕੰਡਕਟਰ ਵਰਦੀ ਪਹਿਨਦਾ ਹੈ।
5. ਗੱਡੀ ਦੇ ਡਰਾਈਵਰ ਅਤੇ ਕੰਡਕਟਰ ਕੋਲ 'ਵੈਲਿਡ ਲਾਈਸੈਂਸ' ਹੈ।
6. ਗੱਡੀ ਦੇ ਡਰਾਈਵਰ ਕੋਲ 5 ਸਾਲ ਦਾ ਤਜ਼ਰਬਾ ਹੈ।
7. ਗੱਡੀ ਦੇ ਡਰਾਈਵਰ ਦਾ 3 ਵਾਰੀ ਤੋਂ ਜ਼ਿਆਦਾ ਚਲਾਣ ਨਹੀਂ ਹੋਇਆ।
8. ਬੱਸ ਦੇ ਉੱਪਰ ਸਕੂਲ ਦਾ ਨਾਂ ਦਾ ਬੋਰਡ, ਰੂਟ ਦਾ ਨਾਂ ਲਿਖਿਆ ਹੈ ਅਤੇ ਬੱਸ ਵਿੱਚ ਫਸਟ ਏਡ ਬਕਸਾਂ ਉਪਲੱਭਦ ਹੈ।
9. ਬੱਸ ਦੇ ਬੱਚਿਆਂ ਦੀ ਓਵਰਲੋਡਿੰਗ (ਡੇਢ ਗੁਣਾਂ ਤੋਂ ਜ਼ਿਆਦਾ) ਨਹੀਂ ਹੈ।
10. ਬੱਸ ਪਲੂਸ਼ਨ ਫਰੀ ਹੈ ਅਤੇ ਪਲੂਸ਼ਨ ਸਰਟੀਫਿਕੇਟ ਲਿਆ ਹੋਇਆ ਹੈ।
11. ਸਕੂਲ ਦੀਆਂ ਬੱਸਾਂ ਦੀ ਸਪੀਡ ਲਿਮਟ ਫੋਲੋ ਕਰਦੀਆ ਹਨ।
12. ਬੱਸਾਂ ਨੂੰ ਰੋਕਣ ਲਈ ਬੱਸ ਸਟਾਫ ਬਣਿਆਂ ਹੋਇਆ ਹੈ।
13. ਸਕੂਲ ਅੰਦਰ ਪਾਰਕਿੰਗ ਦੀ ਥਾਂ ਅਤੇ ਸਕੂਲ ਦੇ ਅੰਦਰ ਹੀ ਬੱਚਿਆਂ ਨੂੰ ਉਤਾਰਿਆਂ ਜਾਂਦਾ ਹੈ।
14. ਸਕੂਲ ਬੱਸ ਲਈ ਵਨ-ਵੇ ਟ੍ਰੈਫਿਕ ਹੈ।
15. ਸਕੂਲ ਅਧਿਕਾਰੀ ਸਕੂਲ ਵਿੱਚ ਆਉਣ ਵਾਲੇ ਟ੍ਰੈਫਿਕ ਨੂੰ ਕੰਟਰੋਲ ਕਰਦੇ ਹਨ।
16. ਸਕੂਲ ਬੱਸਾਂ ਦੇ ਡਰਾਈਵਰਾਂ ਅਤੇ ਕੰਡਕਟਰਾਂ ਵਲੋਂ ਰਿਫਰੈਸ਼ਰ ਕੋਰਸ ਕੀਤੇ ਜਾ ਰਹੇ ਹਨ।

Sanjeev Chandel
ਬਿਆਨ ਕਰਤਾ

ਵੈਰੀਫੀਕੇਸ਼ਨ:

ਤਸਦੀਕ ਕੀਤਾ ਜਾਂਦਾ ਹੈ ਕਿ ਮੇਰੇ ਵਲੋਂ ਦਿੱਤਾ ਗਿਆ ਉਪਰੋਕਤ ਬਿਆਨ ਬਿਲਕੁਲ ਸਹੀ ਅਤੇ ਦਰੁਸਤ ਹੈ। ਇਸ ਵਿੱਚ ਕੋਈ ਵੀ ਗੱਲ ਛੁਪਾ ਕੇ ਨਹੀਂ ਰੱਖੀ ਹੈ।

Sanjeev Chandel
ਬਿਆਨ ਕਰਤਾ

ਸਥਾਨ : ਮੁਕੇਰੀਆਂ

ਮਿਤੀ: 12/5/26

सत्यमेव जयते

INDIA NON JUDICIAL

Government of Punjab

e-Stamp

Certificate No.	:	IN-PB48372393679523Y
Certificate Issued Date	:	12-May-2026 09:53 AM
Certificate Issued By	:	pbvivdogu
Account Reference	:	NEWIMPACC (SV)/ pb7004204/ MUKERIYAN/ PB-HS
Unique Doc. Reference	:	SUBIN-PBPB70042049187644735457 6Y
Purchased by	:	DASMESH PUBLIC SCHOOL MUKERIAN
Description of Document	:	Article 4 Affidavit
Property Description	:	Not Applicable
Area of Property	:	Not Applicable
Consideration Price (Rs.)	:	0 (Zero)
First Party	:	DASMESH PUBLIC SCHOOL MUKERIAN
Second Party	:	Not Applicable
Stamp Duty Paid By	:	DASMESH PUBLIC SCHOOL MUKERIAN
Stamp Duty Amount(Rs.)	:	50 (Fifty only)
Social Infrastructure Cess(Rs.)	:	0 (Zero)
Total Stamp Duty Amount(Rs.)	:	50 (Fifty only)

PREM NATH
Pb. 7004204
Tehsil Complex, Mukerian

Please write or type below this line

PF 0035299433

Statutory Alert:

1. The authenticity of this Stamp certificate should be verified at 'www.shcilestamp.com' or using e-Stamp Mobile App of Stock Holding. Any discrepancy in the details on this Certificate and as available on the website / Mobile App renders it invalid.
2. The onus of checking the legitimacy is on the users of the certificate.
3. In case of any discrepancy please inform the Competent Authority.

SAFE VAHAN SCHEME
INSPECTION REPORT PERFORMA

S.NO	PARTICULARS	INSPECTING REPORT
1.	School bus number	Bus city-40
2.	Permit fitnesscertificate(as per act 083)requirement first aid doc fire extinguisher.	Yes
3.	Stop sign arm towards co-driver side with stop sign (should project out when passenger door is open.	Yes
4.	Speed governor temper proof conveying with the requirement s of rule 11bof mv (a)1989.	Yes
5.	Retracting entry step vehicle should be incapable of motion without folding this step.	Yes
6.	School Bus insignia /color/150 mm golden Brown Band "SCHOOL BUS" must be written on the back and front of the bus. With name and telephone no. of the school (if it is hired bus " ON SCHOOL DUTY "should be written.	Yes
7.	Passenger door with reliable Lock /Emergency doors. Bus should be incapable of motion if any of the door is open and with indication of the same to the Bus driver when passenger door is open the hazard warning lights should operate automatically and stop signal arm should project out the co-driver side.	Yes
8.	Storage racks beneath seats except driver to Driver and last row seats.	Yes
9.	Seats facing passengers step well be provided with the partition preventing child form falling into the step well.	Yes
10.	Window of the bus be fitted with horizontal grills.	Yes
11.	Drivers should have 5 years' experience of Driving.	Yes
12.	Heavy Vehicles and has not been challenged more than twice in a year for the Red light jumping Drink driving etc. drivers conductor with first aid and fire Extinguisher techniques refresher course twice a year. Driver medically fit and should not suffering from any contagious disease. No smoking/drinking of alcohol/chewing of tobacco by Driver/Conductor.	Yes
13.	Compliance of other functions of school authority (a) Children should be trained to open the emergency doors of the Bus. (b) One day refresher course of first aid & fire extinguishing techniques should be conducted by School authority twice a day. (c) School authority should ensure formation of stretch of a road outside of the school.Prominentlymarked "SCHOOL ZONE" by introducing Traffic sign speed limit marking Zebra crossing ,pelican signal to be operated during opening /closing timings to facilitate safe crossing of the children. (d) To ensure speed limit opposite School gate (10 kmph to 25 kmph). (e) To ensure boarding & alighting from the school Bus should be arranges on the school side of the road,So that children do not have to cross the road.	Yes

Signature of Principal

Principal
DASMESH PUBLIC SCHOOL
Chak Alla Baksh, Mukerian
Distt. Hoshiarpur

12/5/26

Mobile No. 9041268099

Signature of Transport Incharge

Mobile No. 9478732775