

ਐਫੀਡੇਵਿਟ

ਮੈਂ ਸੁਮਨ, ਪ੍ਰਿੰਸੀਪਲ ਦਸਮੇਸ਼ ਪਬਲਿਕ ਸਕੂਲ, ਬਿਆਨ ਕਰਦੀ ਹਾਂ ਕਿ ਦਸਮੇਸ਼ ਪਬਲਿਕ ਸਕੂਲ, ਚੱਕ ਅੱਲਾ ਬਖਸ਼, ਮੁਕੇਰੀਆਂ ਵਿਖੇ ਬੱਚਿਆਂ ਨੂੰ ਲਿਆਉਣ ਅਤੇ ਲੈ ਕੇ ਜਾਣ ਲਈ ਟਰਾਂਸਪੋਰਟ ਦਾ ਹੇਠ ਲਿਖੇ ਅਨੁਸਾਰ ਪ੍ਰਬੰਧ ਹੈ। ਸਕੂਲ ਕੋਲ ਬੱਚਿਆਂ ਨੂੰ ਲਿਆਉਣਾ ਅਤੇ ਲੈ ਕੇ ਜਾਣ ਲਈ ਬੱਸਾਂ ਦੀ ਗਿਣਤੀ 40 ਹੈ। ਜਿਹਨਾਂ ਦੇ ਰਜਿਸਟ੍ਰੇਸ਼ਨ ਨੰਬਰ ਹੇਠ ਲਿਖੇ ਅਨੁਸਾਰ ਹਨ-

PB07-Z9980, AA7271, AB7271, AB9695, AE9695, AF5251, AF9695, AL4541, AS1244, AS1246, AS3203, AS3746, AS3747, AS5763, AS7391, AS8392, BG1394, BG1395, BG1396, BG1806, BG2937, BP7042, BP7043, BP8191, BS6198, BS6200, BV3179, BV2968, BV2983, CA9579, CA9583, CB7178, CB7180, CB8117, CD1574, CD1575, CD4569, CG2482, New Bus, New Bus.

1. ਉਪਰੋਕਤ ਬੱਸਾਂ ਹੋਰ ਟਰਾਂਸਪੋਰਟ ਦੇ ਸਾਧਨਾਂ ਕੋਲ ਫਿਟਨੈਸ ਸਰਟੀਫਿਕੇਟ ਹੈ ਅਤੇ ਇਹ ਸੜਕ ਤੇ ਚੱਲਣ ਯੋਗ ਹਨ।
2. ਉਪਰੋਕਤ ਬੱਸਾਂ ਜਾਂ ਹੋਰ ਟਰਾਂਸਪੋਰਟ ਸਾਧਨਾਂ ਕੋਲ ਪਰਮਿਟ ਹੈ।
3. ਉਪਰੋਕਤ ਗੱਡੀਆਂ ਦੇ ਨਾਲ ਕੰਡਕਟਰ ਵੀ ਹੈ।
4. ਗੱਡੀ ਦਾ ਡਰਾਈਵਰ ਅਤੇ ਕੰਡਕਟਰ ਵਰਦੀ ਪਹਿਨਦਾ ਹੈ।
5. ਗੱਡੀ ਦੇ ਡਰਾਈਵਰ ਅਤੇ ਕੰਡਕਟਰ ਕੋਲ 'ਵੈਲਿਡ ਲਾਈਸੈਂਸ' ਹੈ।
6. ਗੱਡੀ ਦੇ ਡਰਾਈਵਰ ਕੋਲ 5 ਸਾਲ ਦਾ ਤਜਰਬਾ ਹੈ।
7. ਗੱਡੀ ਦੇ ਡਰਾਈਵਰ ਦਾ 3 ਵਾਰੀ ਤੋਂ ਜ਼ਿਆਦਾ ਚਲਾਣ ਨਹੀਂ ਹੋਇਆ।
8. ਬੱਸ ਦੇ ਉੱਪਰ ਸਕੂਲ ਦਾ ਨਾਂ ਦਾ ਬੋਰਡ, ਰੂਟ ਦਾ ਨਾਂ ਲਿਖਿਆ ਹੈ ਅਤੇ ਬੱਸ ਵਿੱਚ ਫਸਟ ਏਡ ਬਕਸਾਂ ਉਪਲੱਬਧ ਹੈ।
9. ਬੱਸ ਦੇ ਬੱਚਿਆਂ ਦੀ ਓਵਰਲੋਡਿੰਗ (ਡੇਢ ਗੁਣਾ ਤੋਂ ਜ਼ਿਆਦਾ) ਨਹੀਂ ਹੈ।
10. ਬੱਸ ਪਲੂਸ਼ਨ ਫਰੀ ਹੈ ਅਤੇ ਪਲੂਸ਼ਨ ਸਰਟੀਫਿਕੇਟ ਲਿਆ ਹੋਇਆ ਹੈ।
11. ਸਕੂਲ ਦੀਆਂ ਬੱਸਾਂ ਦੀ ਸਪੀਡ ਲਿਮਟ ਫੋਲੋ ਕਰਦੀਆਂ ਹਨ।
12. ਬੱਸਾਂ ਨੂੰ ਰੋਕਣ ਲਈ ਬੱਸ ਸਟਾਫ ਬਣਿਆਂ ਹੋਇਆ ਹੈ।
13. ਸਕੂਲ ਅੰਦਰ ਪਾਰਕਿੰਗ ਦੀ ਥਾਂ ਅਤੇ ਸਕੂਲ ਦੇ ਅੰਦਰ ਹੀ ਬੱਚਿਆਂ ਨੂੰ ਉਤਾਰਿਆ ਜਾਂਦਾ ਹੈ।
14. ਸਕੂਲ ਬੱਸ ਲਈ ਵਨ-ਵੇ ਟ੍ਰੈਫਿਕ ਹੈ।
15. ਸਕੂਲ ਅਧਿਕਾਰੀ ਸਕੂਲ ਵਿੱਚ ਆਉਣ ਵਾਲੇ ਟ੍ਰੈਫਿਕ ਨੂੰ ਕੰਟਰੋਲ ਕਰਦੇ ਹਨ।
16. ਸਕੂਲ ਬੱਸਾਂ ਦੇ ਡਰਾਈਵਰਾਂ ਅਤੇ ਕੰਡਕਟਰਾਂ ਵਲੋਂ ਰਿਫਰੈਸ਼ਰ ਕੋਰਸ ਕੀਤੇ ਜਾ ਰਹੇ ਹਨ।

ਬਿਆਨ ਕਰਤਾ

ਵੈਰੀਫੀਕੇਸ਼ਨ:

ਤਸਦੀਕ ਕੀਤਾ ਜਾਂਦਾ ਹੈ ਕਿ ਮੇਰੇ ਵਲੋਂ ਦਿੱਤਾ ਗਿਆ ਉਪਰੋਕਤ ਬਿਆਨ ਬਿਲਕੁਲ ਸਹੀ ਅਤੇ ਦਰੁਸਤ ਹੈ। ਇਸ ਵਿੱਚ ਕੋਈ ਵੀ ਗੱਲ ਛੁਪਾ ਕੇ ਨਹੀਂ ਰੱਖੀ ਹੈ।

ਸਥਾਨ : ਮੁਕੇਰੀਆਂ

ਮਿਤੀ: 06-05-2025


ਬਿਆਨ ਕਰਤਾ



INDIA NON JUDICIAL
Government of Punjab

e-Stamp

Certificate No. : IN-PB31793545658345X
Certificate Issued Date : 05-May-2025 11:01 AM
Certificate Issued By : pbvvdogu
Account Reference : NEWIMPAGC (SV)/ pb7004204/ MUKERIYAN/ PB-HS
Unique Doc. Reference : SUBIN-PBPB700420461971145200943X
Purchased by : SUMAN WO LOKESH VIMAL SHUKLA
Description of Document : Article 4 Affidavit
Property Description : Not Applicable
Area of Property : Not Applicable
Consideration Price (Rs.) : 0
(Zero)
First Party : SUMAN WO LOKESH VIMAL SHUKLA
Second Party : Not Applicable
Stamp Duty Paid By : SUMAN WO LOKESH VIMAL SHUKLA
Stamp Duty Amount(Rs.) : 50
(Fifty only)
Social Infrastructure Cess(Rs.) : 0
(Zero)
Total Stamp Duty Amount(Rs.) : 50
(Fifty only)



Please write or type below this line

HF 0023802884

Statutory Alert

1. The authenticity of this Stamp certificate should be verified at www.shoostamp.gov.in or using a Stamp Mobile App of your choice.
2. The user of checking the legitimacy is on the users of the certificate.
3. In case of any discrepancy please inform the competent authority.

**SAFE VAHAN SCHEME
INSPECTION REPORT PERFORMA**

S.NO	PARTICULARS	INSPECTING REPORT
1.	School bus number	TOTAL Buses 40
2.	Permit fitness certificate (as per act 083) requirement first aid doc fire extinguisher.	Ys
3.	Stop sign arm towards co-driver side with stop sign (should project out when passenger door is open).	Ys
4.	Speed governor temper proof conveying with the requirements of rule 11 of mv (a) 1989.	Ys
5.	Retracting entry step vehicle should be incapable of motion without folding this step.	Ys
6.	School Bus insignia /color/150 mm golden Brown Band "SCHOOL BUS" must be written on the back and front of the bus. With name and telephone no. of the school (if it is hired bus "ON SCHOOL DUTY" should be written).	Ys
7.	Passenger door with reliable Lock /Emergency doors. Bus should be incapable of motion if any of the door is open and with indication of the same to the Bus driver when passenger door is open the hazard warning lights should operate automatically and stop signal arm should project out the co-driver side.	Ys
8.	Storage racks beneath seats except driver to Driver and last row seats.	Ys
9.	Seats facing passengers step well be provided with the partition preventing child from falling into the step well.	Ys
10.	Window of the bus be fitted with horizontal grills.	Ys
11.	Drivers should have 5 years' experience of Driving.	Ys
12.	Heavy Vehicles and has not been challenged more than twice in a year for the Red light jumping Drink driving etc. drivers conductor with first aid and fire Extinguisher techniques refresher course twice a year. Driver medically fit and should not suffering from any contagious disease. No smoking/drinking of alcohol/chewing of tobacco by Driver/Conductor.	Ys
13.	Compliance of other functions of school authority (a) Children should be trained to open the emergency doors of the Bus. (b) One day refresher course of first aid & fire extinguishing techniques should be conducted by School authority twice a day. (c) School authority should ensure formation of stretch of a road outside of the school. Prominently marked "SCHOOL ZONE" by introducing Traffic sign speed limit marking Zebra crossing, pelican signal to be operated during opening /closing timings to facilitate safe crossing of the children. (d) To ensure speed limit opposite School gate (10 kmph to 25 kmph). (e) To ensure boarding & alighting from the school Bus should be arranged on the school side of the road, So that children do not have to cross the road.	Ys

Signature of Principal
Principal
Chak Alla Baksh, Mukerian
Mobile No. 9878289562

Signature of Transport Incharge
Mobile No. 9878289562