BUILDING SAFETY CERTIFICATE

File No. 24 Date: 12-04-2024

It is certified that the existing building Dasmesh Public School at Chak Alla Baksh, Tehsil Mukerian, Distt. Hoshiarpur is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	3	3	3	3	N/A	N/A

The building is owned/occupied by Dasmesh Public School at Chak Alla Baksh, Tehsil Mukerian, Distt. Hoshiarpur have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Sub Divisional Engineer, Provincial Sub Division, PWD (B & R) Branch, Mukerian, Distt. Hoshiarpur on 12-04-2024 in the presence of S. Satpal Singh (Manager) at Dasmesh Public School at Chak Alla Baksh, Tehsil Mukerian, Distt. Hoshiarpur and that the building/premises is fit for occupancy for running school with effect from 01-04-2024 for a period of one year in accordance with rule and subject to compliance of the specific conditions as appended.

- 1. Water should not be allowed to stand around the building and on the roofs.
- 2. If any kind on crack occurs in the building then that place should be vacated immediately and its repair should be done immediately.
- 3. The quality of the material used in any type of construction will be the responsibility of concerned school.
- 4. In addition to the attached map, if you want to do additional construction, then its approval should be taken from this department.
- 5. According to Director Journal School Education Department Punjab and State Project Sarv Shiksha Abhiyan letter no. 75444 dated: 06-11-2009 fire extinguishers should be kept in working condition in the school. A copy of the Fire Safety Certificate of the year 2024-25 should be given in this office. All responsibility for any untoward incident will be the responsibility of school concerned.

Issued on 12-04-2024 at Mukerian by Sub Divisional Engineer, Provincial Sub Division, PWD (B & R)

Branch, Mukerian, Distt. Hoshiarpur.

1 0 SEP 2024

Signature with Seal: Davinder Singh

Name: Davinder Singh

Designation: Sub Divisional Engineer

Name & Address of Department /Office: Sub Divisional Engineer,
Provincial Sub Division, PWD (B & R)
Branch, Mukerian, Distt. Hoshiarpur.

Franslation Copy of the Document Produced

ATTESTED
ANJU CHOWDHARY

Notary Public Mukerian

From

Sub Divisional Engineer Provincial Sub-Division, PWD (B&R) Branch, Mukerian.

To

Principal

Dashmesh Public School, Chak Alla Baksh, Mukerian.

No. 260

Dated: 09-09-2024

Subject:

Building Safety Certificate for the Year 2024-25

(Principal Dashmesh Public School Chak Alla Baksh Mukerian (Hoshiarpur)

Ref.

Yours office Letter No. DPS/2024-25/88 Dated 06-09-2024 and in continuation

of this office letter no.24 Dated 12.04.2024

The above Said School Building has been Inspected Visually by undersigned & Concerned J. E in Presence of Sh. Satpal Singh (Manager) of Dashmesh Public School. This School Building has 4 No. Blocks with ground floor, first floor, and second floor, which looks fine and building has been found fit for Normal Use as School Building for Year 2024-25. The building safety certificate of the school is issued as per the following instructions:-

- Water should not be allowed to stand around the building and on the roofs. 1.
- If any kind of crack occurs in the building, then that place should be vacated 2 immediately and its repair should be done immediately.
- The responsibility of the material used and Structure of design including 3. Foundation in any kind of construction will be that of the concerned school because the construction of the school was made in the supervision of School Management Committee.
- In addition to the attached map. if you want to do additional construction, then 4. its approval should be taken from this department.
- Follow the building related instructions given to you during the inspection. 5. According to Director Journal School Education Department Punjab and State Project Sarv Shiksha Abhiyan Letter No. 75444 dated: 06.11.2009 fire extinguishers should be kept in working condition in the school. Any untoward accident will be the responsibility of the concerned school.
- In Case any additional Extension and Modification of this Building is to be caused 6. out the same be carried out under the supervision of a technical qualified engineer and this certificate may again be obtained after completion from the undersigned.
- In Case Building is affected by flood or there is any settlement of walls 7. foundations or sagging of rooms etc. immediate inspection of undersigned be arranged to check the stability & Safety of the building.
- In case of cracks and settlement in the building, the building should be vacated 8. immediately.
- If you make any changes in these conditions at your own level, the Department 9. of Public Works will reserve the right to cancel the NOC issued to you without any notice.

DA/Nil

Sub Divisional Engineer Provincial Sub-Division, PWD (B&R) Branch, Mukerian